


MASTER CYLINDERS & AIR PACKS



EBS MASTER CYLINDERS - BOSCH

| | | | | | | | |
|---|---------------------------------|-----------------------------|-----------------------------|---|---------------------------------|-----------------------------|--|
|  | | | |  | | | |
| Alternative Part No | 0483004201000 0014318514 | 0483004401000 0014317214 | 0483004601000 0014317114 | Alternative Part No | 0483004501000 0014317514 | 0483004701000 0014317314 | |
| Repair Kits | EKBO.6 (OE Ref = 1487010196) | | | Repair Kits | EKBO.6 (OE Ref = 1487010196) | | |

EBS MASTER CYLINDERS - FAG / FTE

| | | | | | | | |
|---|--|---|---|--|--|---|--|
| 16.35.1031 | | 16.35.1030 | | 16.35.1034 | | 16.35.1003 | |
|  | |  | |  | |  | |
| Alternative Part No | 758188.01SP | Alternative Part No | KG190072.01 0012955206 0012959606 | Alternative Part No | KG190084.0.2 | Alternative Part No | KG19098.16 6672900212 |
| Repair Kits | --- | Repair Kits | --- | Repair Kits | --- | Repair Kits | EKFA.8 (OE Ref = RK19799 / 0002901812) |
| 16.35.1004 | | 16.35.1036 | | 16.35.1005 | | --- | |
|  | |  | |  | |  | |
| Alternative Part No | KG20001.0.8 0012959106 | Alternative Part No | KG20001.0.10 0012959506 | Alternative Part No | KG20010.0.1 0012950106 | Alternative Part No | KG2201911 1278342 0012957406 |
| Repair Kits | EKFA.2 | Repair Kits | EKFA.2 | Repair Kits | EKFA.6 | Repair Kits | EKFA.26 (OE Ref = RK22757 / 0002901212) |
| 16.35.1006 | | 16.35.1000 | | 16.35.1010 | | 16.35.1011 | |
|  | |  | |  | |  | |
| Alternative Part No | KG22019.1.4 6732950006 | Alternative Part No | KG22026.0.1 1291190 | Alternative Part No | KG22027.0.2 81307156140 | Alternative Part No | KG22028.0.2 81307156141 |
| Repair Kits | EKFA.9 (OE Ref = RK22762 / 0002904012) | Repair Kits | EKFA.5 | Repair Kits | EKFA.10 (OE Ref = RK22761 / 81307156144) | Repair Kits | EKFA.11 (OE Ref = RK22760 / 81307156143) |

EBS MASTER CYLINDERS - FAG / FTE





| | | | | | | | |
|---|---|---|---|--|--|---|--|
| 16.35.1018 | | 16.35.1007 | | 16.35.1026 | | 16.35.1027 | |
|  | |  | |  | |  | |
| Alternative Part No | KG23017.1.1 42063311 | Alternative Part No | KG23021.1.3 0012952506 0012955306 | Alternative Part No | KG23027.0.1 81307156119 | Alternative Part No | KG23030.0.2 81307156135 |
| Repair Kits | EKFA.30 | Repair Kits | EKFA.12 (OE Ref = RK23719 / 0002902367) | Repair Kits | EKFA.13 (OE Ref = RK23722 / 81307156113) | Repair Kits | EKFA.13 (OE Ref = RK23722 / 81307156113) |
| 16.35.1023 | | 16.35.1028 | | 16.35.1043 | | 16.35.1013 | |
|  | |  | |  | |  | |
| Alternative Part No | KG2394.1.12 1291509 0691041 42558437 02479001 | Alternative Part No | KG2395.1.7 0012952906 | Alternative Part No | KG2397.1.14 | Alternative Part No | KG2397.1.19 3127318 3953328 6028036 6771722 6857432 |
| Repair Kits | EKFA.35 | Repair Kits | EKFA.40 | Repair Kits | --- | Repair Kits | EKFA.22 (OE Ref = RK23725 / 273443 / 276649 / 6771724) |
| --- | | 16.35.1001 | | 16.35.1014 | | --- | |
|  | |  | |  | |  | |
| Alternative Part No | KG2397.1.20 5010136472 | Alternative Part No | KG250001.0.2 109740 395161 96392 | Alternative Part No | KG250004.0.2 1361136 | Alternative Part No | KG250005.0.1 1255105 |
| Repair Kits | EKFA.14 (OE Ref = RK23733 / 5001835243) | Repair Kits | EKFA.15 (OE Ref = RK25717 / 1237496 / 696264) | Repair Kits | EKFA.18 | Repair Kits | EKFA.19 |
| 16.35.1012 | | --- | | --- | | --- | |
|  | |  | |  | |  | |
| Alternative Part No | KG250006.0.2 81307156132 | Alternative Part No | KG250009.1.1 4853409 | Alternative Part No | KG25011.01 | Alternative Part No | KG2595.1.5 |
| Repair Kits | EKFA.16 (OE Ref = RK25718 / 81307156145) | Repair Kits | EKFA.20 | Repair Kits | --- | Repair Kits | --- |

MASTER CYLINDERS & AIR PACKS

EBS MASTER CYLINDERS - FAG / FTE


| | | | | | | | |
|---|---------------------------------------|---|--|--|--|---|---------------------------|
| 16.35.1015 | | --- | | 16.35.1032 | | 16.35.1021 | |
|  | |  | |  | |  | |
| Alternative Part No | KG2595.1.4 292962 355973 | Alternative Part No | KG259615 446414 | Alternative Part No | KG260411 0012953006 0012950806 | Alternative Part No | KG26703.1.1 8282211000 |
| Repair Kits | EKFA.3 (OE Ref = RK25703 / 550440) | Repair Kits | EKFA.27 (OE Ref = RK25705 / 639088) | Repair Kits | EKFA.25 (OE Ref = RK26504 / 0005866029) | Repair Kits | EKFA.33 |

| | | | | | | | |
|---|---|---|-------------|--|--|---|-------------------------------|
| 16.35.1002 | | 16.35.1041 | | --- | | 16.35.1017 | |
|  | |  | |  | |  | |
| Alternative Part No | KG28010.0.1 223443 372589 894880 | Alternative Part No | KG28011.0.1 | Alternative Part No | KG28011.0.1 0260242 0390487 0751820 | Alternative Part No | KG28012.0.1 1628218 |
| Repair Kits | EKFA.17 (OE Ref = RK28706 / 1237505) | Repair Kits | --- | Repair Kits | EKFA.24 (OE Ref = 1237508 / RK28707) | Repair Kits | EKFA.23 (OE Ref = RK28712) |

| | | | | | | | |
|---|---|---|--|--|-----------------------|---|------------------------|
| 16.35.1016 | | 16.35.1025 | | 16.35.1009 | | 16.35.1008 | |
|  | |  | |  | |  | |
| Alternative Part No | KG28014.1.1 1581209 1614351 1620462 1669488 | Alternative Part No | KG28019.4.2 20553587 20835246 8172824 | Alternative Part No | KG3106.0.1 4853408 | Alternative Part No | KG3107.0.1 41211005 |
| Repair Kits | EKFA.7 EKFA.1.1 EKFA.1 | Repair Kits | EKFA.37 | Repair Kits | EKFA.4 | Repair Kits | EKFA.21 EKFA.21.1 |





| | | | | | | | |
|---|------------------------|---|---------------------------|--|----------------------------|---|----------------------------|
| 16.35.1037 | | 16.35.1029 | | 16.35.1019 | | 16.35.1020 | |
|  | |  | |  | |  | |
| Alternative Part No | KG3107.1.1 41285356 | Alternative Part No | KG3401.0.1 81307156051 | Alternative Part No | KN28013.A.1 81307166020 | Alternative Part No | KN28014.C.1 81307166082 |
| Repair Kits | EKFA.21 | Repair Kits | EKFA.41 | Repair Kits | EKFA.31 | Repair Kits | EKFA.32 |

EBS MASTER CYLINDERS - FAG / FTE

| | | | | | | | |
|---|-----------|---|-------------------------|--|------------|---|---------------|
| 16.35.1042 | | 16.35.1024 | | 16.35.1022 | | 16.35.1038 | |
|  | |  | |  | |  | |
| Alternative Part No | KN28022D1 | Alternative Part No | KN28027A1 0022950707 | Alternative Part No | KN3406.E66 | Alternative Part No | MKG190110.4.2 |
| Repair Kits | --- | Repair Kits | EKFA.36 | Repair Kits | EKFA.34 | Repair Kits | --- |

| | | | | | |
|---|--------------|---|--------------|--|------------|
| 16.35.1040 | | 16.35.1039 | | 16.35.10000 | |
|  | |  | |  | |
| Alternative Part No | MKG20003.4.2 | Alternative Part No | MKG23852.4.3 | Alternative Part No | KG2597.1.2 |
| Repair Kits | --- | Repair Kits | --- | Repair Kits | --- |

EBS MASTER CYLINDERS - KNORR BREMSE

| | | | | | | | |
|---|-----------|---|---------|--|------------|---|------------|
| --- | | --- | | 16.02.2011 | | 16.02.2123 | |
|  | |  | |  | |  | |
| Alternative Part No | 1189421SP | Alternative Part No | 1194186 | Alternative Part No | K022011N00 | Alternative Part No | K032123N50 |
| Repair Kits | --- | Repair Kits | --- | Repair Kits | --- | Repair Kits | --- |

| | | | | | | | |
|---|---------|---|-----------------------------------|--|-------------|---|-------------|
| 16.02.3984 | | 16.35.1031 | | 16.35.1033 | | 16.35.1035 | |
|  | |  | |  | |  | |
| Alternative Part No | K013984 | Alternative Part No | 758188.01SP 4804129 FBU9864 | Alternative Part No | KN38017.3.5 | Alternative Part No | KN38017.3.6 |
| Repair Kits | --- | Repair Kits | --- | Repair Kits | --- | Repair Kits | --- |

MASTER CYLINDERS & AIR PACKS

EBS MASTER CYLINDERS - KONGSBERG

| | | | | | | | |
|---|---|---|--|--|--|---|---|
| 16.62.3104 | | 16.62.3105 | | 16.62.3106 | | 16.62.3109 | |
|  | |  | |  | |  | |
| Alternative Part No | 623104AM | Alternative Part No | 623105AM | Alternative Part No | 623106AM 5000792359 | Alternative Part No | 623109AM 81307156120 |
| Repair Kits | EKPP.28.1 | Repair Kits | EKPP.28.2 | Repair Kits | EKPP.28.12 (OE Ref = 626243) | Repair Kits | EKPP.28.4 (OE Ref = 625977 / 81307156139) |
| 16.62.3160 | | 16.62.4248 | | 16.62.4502 | | 16.62.4503 | |
|  | |  | |  | |  | |
| Alternative Part No | 623160AM 81307156119 | Alternative Part No | 624248AM 5010251357 | Alternative Part No | 624502AM 1358801 | Alternative Part No | 624503AM 1361136 |
| Repair Kits | EKPP.28.5 (OE Ref = 625976 / 81307156138) | Repair Kits | EKPP.28.6 (OE Ref = 626165) | Repair Kits | EKPP.28 (OE Ref = 623157 / 550464) | Repair Kits | EKPP.28 (OE Ref = 623157 / 550464) |
| 16.62.5536 | | 16.62.5826 | | 16.62.6159 | | 16.62.6564 | |
|  | |  | |  | |  | |
| Alternative Part No | 625536AM | Alternative Part No | 625826AM ACHD274 | Alternative Part No | 626159AM 5001834842 | Alternative Part No | 626564AM ACHD722 |
| Repair Kits | --- | Repair Kits | EKPP.28.7 | Repair Kits | EKPP.28.8 EKPP.28.8.RES | Repair Kits | EKPP.28.7 (OE Ref = 626608 / AMPA852) |
| 16.62.6565 | | 16.62.6760 | | 16.62.6761 | | 16.62.6762 | |
|  | |  | |  | |  | |
| Alternative Part No | 626565AM | Alternative Part No | 626760AM 1339412 | Alternative Part No | 626761AM 1348734 | Alternative Part No | 626762AM 1395485 |
| Repair Kits | --- | Repair Kits | EKPP.28 (OE Ref = 627200 / 1373531)) | Repair Kits | EKPP.28.10 (OE Ref = 627202 / 1373533) | Repair Kits | EKPP.28.11 (OE Ref = 627201 / 1373532) |

EBS MASTER CYLINDERS - KONGSBERG

| | | | |
|---|----------|---|-------------------------------------|
| 16.62.7233 | | 16.63.1522 | |
|  | |  | |
| Alternative Part No | 627233AM | Alternative Part No | 631522AM 1000179039AM 1800442 |
| Repair Kits | --- | Repair Kits | --- |

EBS MASTER CYLINDER AND RESERVOIR - RENAULT

| | |
|--|------------|
| 16.62.6159COM | |
|  | |
| Alternative Part No | 5010260052 |
| Repair Kits | --- |


EBS MASTER CYLINDERS - WABCO

| | | | | | | | |
|---|------------|---|------------|--|------------|---|------------|
| 16.01.1520 | | --- | | R16.01.2004 | | R16.01.2006 | |
|  | |  | |  | |  | |
| Alternative Part No | 4700125202 | Alternative Part No | 9213990120 | Alternative Part No | 9281000042 | Alternative Part No | 9281000067 |
| Repair Kits | EKWA.18.4C | Repair Kits | EKWA.5 | Repair Kits | 9741005332 | Repair Kits | 9741005332 |

| | | | | | |
|-----------------------------------|--------------------------|---|------------|--|------------|
| 16.01.2006WR | | 16.01.3902 | | 16.01.4008 | |
| MASTER CYLINDER WITHOUT RESERVOIR | |  | |  | |
| Alternative Part No | 9281000067 9281000042 | Alternative Part No | 9650019022 | Alternative Part No | 9740100080 |
| Repair Kits | --- | Repair Kits | --- | Repair Kits | --- |

MASTER CYLINDERS & AIR PACKS

EBS BOSCH KITS



EBS FAG / FTE KITS



EBS FAG / FTE KITS



MASTER CYLINDERS & AIR PACKS

EBS KONGSBERG KITS



EBS KNORR BREMSE KITS



EBS WABCO KITS

